3/17/2019 To-Do Print



14408 Whittier Boulevard suite B9 • Whittier, CA 90605 • Phone: (562)755-7790

Print-date:

3-17-2019

Inh: 1st story Addition

Job. 1st story Addition	
Address:	
To-Do Details: 25 Point Quality control Inspection	
Marked Complete: Create	ed by Robert Leon on 3-16-2019
Priority: Due Date: Sun, Jul 07	
Description This 25 point Quality Control inspection is to be completed by Superintendent and Project manager during the construction trade is to be inspected and approved at the end of the viscosity of the project.	
1.Foundation visually inspect,forms removed ,correct floor elevation , landing ,steps, foundation access complete job site.	ed, excess dirt removed from
2.Framing inspect addition size, ceiling heights, floor sheeting, wood quality, fascia eaves, door opening size , wind installed.	ndow opening size Hardware
3.Roof visually inspect style, color, flashings painted, nail shiners and water tested roof 15 minutes sprinkler test	
4.Electrical visually inspect outlets,switch, fixture locations , nail guards,circuits.	
5.Plumbing inspection Visually inspect location of supply,drains location , leaks and nail guards	
6.Mechanical visually inspect, ducting, unit, gas line, electrical, confirm Herrs report ordered ducting over 40 lf	
7.Drywall visual inspect all drywall, texture, window or door openings, patching;	
8.Molding visually inspected for cuts, completed, casing, base.	
9.Interior exterior Doors visually inspect all interior exterior doors, adjust thresholds, weather stripping, open and	close properly
10.Painting interior visually inspect all interior painting, walls, ceilings, caulking ,drips, sheen, color, clean up.	
11. Windows visually inspect all windows, open and close properly, locks properly, stickers removed, tracks clean	ned window screens.installed.
12.Cabinets visually inspect finish color, blemishes, hardware installed open and close properly.	

Tags:

Robert Leon, Steven Baker